



**Figure 6.1-1. Aerial view of the dam and ancillary facilities.**



**6.1-2. View of the Oroville Dam spillway from Oroville Dam Road.**



**Figure 6.1-3. View of Oroville Dam from Thermalito Forebay (from South Forebay Recreation Area).**



Figure 6.1-4a. Nelson Bar Car-top BR: Pool elevation = 900 ft.



Figure 6.1-4b. Nelson Bar Car-top BR: Pool elevation = 830 ft.



Figure 6.1-4c. Nelson Bar Car-top BR: Pool elevation = 710 ft.





Figure 6.1-5a: Bidwell Bar Bridge (Highway 162): Pool elevation = 900 ft.



Figure 6.1-5b: Bidwell Bar Bridge (Highway 162): Pool elevation = 830 ft.



Figure 6.1-5c: Bidwell Bar Bridge (Highway 162): Pool elevation = 710 ft.





Figure 6.1-6a. Loafer Creek BR: Pool elevation = 900 ft.





Figure 6.1-6b. Loafer Creek BR: Pool elevation = 830 ft.




Figure 6.1-6c. Loafer Creek BR: Pool elevation = 710 ft.



**Figure 6.2-1. Transmission line towers behind Diversion Pool.**





**Figure 6.4-1. Feather River Fish Hatchery and Fish Diversion Dam.**



**Figure 6.4-2. Thermalito Afterbay outlet.**



**KOP MR-1: Nelson Bar Car-top Boat Ramp: June 13, 2002. Pool elevation = 830 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-1: Nelson Bar Car-top Boat Ramp: October 22, 2002. Pool elevation = 709 feet (exceedance percentage for late-October is 85 to 90 percent)**





**KOP MR-2: Lime Saddle Boat Ramp: June 13, 2002. Pool elevation = 830 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-2: Lime Saddle Boat Ramp: October 22, 2002. Pool elevation = 709 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-3: Lime Saddle Peninsula: June 13, 2002. Pool elevation = 830 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-3: Lime Saddle Peninsula: October 22, 2002. Pool elevation = 710 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-4: Foreman Creek Car-top Boat Ramp: June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-4: Foreman Creek Car-top Boat Ramp: October 21, 2002. Pool elevation = 710 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-5: Canyon Creek Bridge (west): June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-5: Canyon Creek Bridge (west): October 21, 2002. Pool elevation is 710 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-6: Bidwell Bar Bridge (Highway 162): June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-6: Bidwell Bar Bridge (Highway 162): October 21, 2002. Pool elevation = 710 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-7: Stringtown Car-top Boat Ramp (northeast): June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-7: Stringtown Car-top Boat Ramp (northeast): October 21, 2002: Pool elevation = 710 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-8: Bidwell Canyon Boat Ramp: June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-8: Bidwell Canyon Boat Ramp: October 21, 2002. Pool elevation = 710 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-9: Bidwell Canyon Marina: June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-9: Bidwell Canyon Marina: October 21, 2002. Pool elevation = 710 feet (exceedance percentage for late October is 85 to 90 percent)**



**KOP MR-10: Bidwell Canyon Cove to South: October 22, 2002. Pool elevation = 709 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-11: Loafer Creek Boat Ramp: June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**




**KOP MR-11: Loafer Creek Boat Ramp: October 22, 2002. Pool elevation = 709 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-12: Lake Oroville Visitors Center Tower: June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-12: Lake Oroville Visitors Center Tower: October 22, 2002. Pool elevation = 709 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-13: Oroville Dam Visitors Area (view looking west): June 12, 2002. Pool elevation = 831 feet (exceedance percentage for mid-June is 75 to 80 percent) (831 feet)**



**KOP MR-13: Oroville Dam Visitors Area (view looking west): October 22, 2002. Pool elevation = 709 feet (exceedance percentage for late October is 85 to 90 percent)**





**KOP MR-14: Spillway Boat Ramp: June 11, 2002. Pool elevation = 832 feet (exceedance percentage for mid-June is 75 to 80 percent)**



**KOP MR-14: Spillway Boat Ramp: October 22, 2002. Pool elevation = 709 feet (exceedance percentage for late October is 85 to 90 percent)**





KOP TD-1: Oroville Dam Road - June 11, 2002 (view of spillway).





KOP TD-2: Diversion Pool Day Use Area - June 11, 2002





KOP TD-3: North Thermalito Forebay Recreation Area - June 11, 2002





**KOP TD-4: South Thermalito Forebay Recreation Area - June 11, 2002**





KOP TA-1: Larkin Road Day Use Area - June 11, 2002




KOP TD-2: Monument Hill Day Use Area - June 11, 2002





KOP BR-1: Feather River Nature Center - June 11, 2002



KOP BR-2: Thermalito Afterbay Outlet - June 11, 2002





KOP OWA-1: One-Mile Campground - November 7, 2002



**KOP OWA-2: OWA Bird Viewing Area - November 7, 2002**

